



WYTWÓRNIA SPRZĘTU KOMUNIKACYJNEGO  
„PZL-ŚWIDNIK”

**LIST  
OF SERVICE LETTERS  
AND BULLETINS  
FOR  
PZL W-3A HELICOPTERS  
OPERATED  
IN PHILIPPINES MILITARY AVIATION**

**Doc. No. WB-3PH**

**CONTENTS**

**1. LIST OF SERVICE LETTERS ..... 3**

**2. LIST OF BULLETINS ..... 4**

# „PZL-ŚWIDNIK”

## LIST OF SERVICE LETTERS

Item	Service Letter No.	Subject	Effectivity	Date of approved	Revision number and its approval date	Language version
1.	LS-012/2013	Operation of helicopters without Movable MR Blade Droop Stops P/N 37.21.800.00.00.	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	05.02.2013		P, E
2.	LS-013/2013	Replacement of Access Cover P/N 37.17.369.00.00 (with slots) with Access Cover P/N 30.15.272.00.01 (without slots).	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	12.06.2013		P, E
3.	LS-026/2013	Restoring Operation of Helicopters with Movable MR Blade Droop Stops.	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	28.10.2013		P, E
4.	LS-034/2013	Rework of riveted joint in Plate P/N 30.13.000.15.01 to comply with tail boom structure.	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	22.10.2013		P, E
5.	LS-040/2013	Rear Tip Cap P/N 30.29.005.20.05 of PZL W-3A Helicopter Main Rotor Blade P/N 30.29.000.00.03.	Main Rotor Blade, S/N 30.09.673	22.11.2013		P, E

# „PZL-ŚWIDNIK”

## LIST OF BULLETINS

Item	Bulletin No.	Subject	Effectivity	Date of approved	Revision number and its approval date	Language version
1.	K-31-12-01/PH	1. Installation of additional ventilation system in LH avionics compartment and tail boom. 2. Updating helicopter manuals.	PZL W-3A helicopters: -S/N 31.09.19÷22 - installation; - All helicopters - manuals updating	04.12.2012		P, E
2.	K,E-31-12-02/PH	1. Installation of SC50 inverter instead of PC-351. 2. Updating operation and maintenance manuals.	PZL W-3A helicopters: -S/N 31.09.19÷22 - installation; - All helicopters - manuals updating	27.11.2012		P, E
3.	E-31-13-03/PH	Updating Flight Manual, Doc. No. AE-31.09.19.0 RFM.	All PZL W-3A helicopters	21.02.2013		P, E
4.	BO-31-13-04/PH Mandatory	One-time inspection of tail rotor pylon plate for cutout ensuring required clearance for tail rotor control cables.	PZL W-3A Helicopters (from S/N 31.09.19 to 31.09.26)	11.10.2013		P, E
5.	BS-31-13-05/PH	Updating Maintenance Manual, Doc. No. AE-31.09.19.0 MM.	All PZL W-3A helicopters	16.01.2014		P, E
6.	BE-31-16-06/PH	Updating Helicopter Maintenance Manual, Doc. No. AE-31.09.19.0 MM.	All PZL W-3A helicopters	13.03.2017		P, E
7.	BK,E-31-17-07/PH	1. Installation of electronic backup control units, type ALRT-2E, on the PZL-10W engines. 2. Updating helicopter manuals.	PZL W-3A helicopters: - for installation – in accordance with Purchase Order; - for updating manuals - all	03.07.2017		P, E
8.	BK,E-31-17-08/PH	1. Installation of external cargo sling. 2. Installation of rappelling system. 3. Installation of handrails at cabin doors. 4. Installation of jump seat. 5. Installation of rescue basket. 6. Updating helicopter manuals. 7. Introducing the DG-64M cargo hook Log Book.	PZL W-3A helicopters: - for installation - in accordance with Purchase Order; - for updating manuals - all	14.09.2017		P, E
9.	BO-31-18-09/PH Mandatory	Inspection of bellcrank assy P/N 30.42.010.00.00.	All PZL W-3A helicopters	29.03.2018		P, E

# „PZL-ŚWIDNIK”

## LIST OF BULLETINS

Item	Bulletin No.	Subject	Effectivity	Date of approved	Revision number and its approval date	Language version
10.	BO-31-18-10/PH Mandatory	Inspection of vibration absorber star P/N 30.23.005.01.04.	All PZL W-3A helicopters	29.03.2018		P, E
11.	BO-31-18-11/PH Mandatory	Inspection of WR-3 main transmission case.	All PZL W-3A helicopters	18.04.2018		P, E